

# MSHEAR Binary Patch 0531-01

R.W. Busby 26 Sep 99  
Caltech/USGS TriNet Seismic Network

An archive file `msbp990926.slip.lzh` is available to correct an error in SLIP communication links that can render the link inoperable. This patch applies to MSHEAR 36/09-0531. It is also backwards compatible to all previous versions of MSHEAR. It is the first patch of this release.

## ***Description of the problem***

The datalogger enters a condition whereby all SLIP communication is disabled. The system sends IP packets out the serial port but no packets are accepted in return. The serial port of the datalogger is not polled for input and hence no incoming slip packets are received. The `ifslip` process transmitting packets monopolizes the serial port and does not allow the `ifslip` process receiving packets access.

In our case, the trigger for entering the problem state was the onset of acknowledges to the SEC comlink during a period when the PRI comlink was still retransmitting frequently but receiving no acknowledgments. An error in the configuration parameters exacerbated the situation by configuring the comlink resend packet window size to be six packets instead of two, when used with a very short resend timeout of 2 seconds. (See configuration details below) In lab simulations, we used `ws=16`, `resendpkts=6` and `resend=10` for normal operations and could trigger the problem state by changing `resend=2` via the option K of the `aqshell` menu. In our case, killing the `dacommo` process could reactivate the link.

The flooding option of a comlink does not cause the slip driver to hang. It seems gross overload of packets to the driver causes it to discard packets and it does not hang. There appear to be only certain conditions in which the driver attempts to keep up transmission at the expense of reception.

Clear indication of the problem is identified through the `slipstat` reports. A view of this status at 5 minute intervals revealed the outbound packets increased while the inbound packets do not. Also, the number of polls of the serial port do not increase. See example diagnostic output in the diagnostic details below.

## ***Solution to the Problem***

A revised slip driver (`ifslip`) works in combination with a revised serial port descriptor (5x8530) to correctly arbitrate for the serial port. The serial port driver is available for Q4120 and Q730. A version for Q680 systems is not yet available. The new slip driver will work with older versions of the serial port descriptor (including the Q680 version) to avoid the error, though better performance is achieved with the new combination. The revised files as offered as a binary `lharc` archive at;

<ftp://quake.geo.berkeley.edu/pub/quanterra/mshear/release/msbp990926.slip.lzh>

This archive includes a copy of the old version and the new version of each module, as well as update the file actually used by the system to the new version.

To install the archive, transfer the binary file to the datalogger (to `/h0/HOLDING`). Extract the file by entering;

```
chd /h0
lharc -xf holding/msbp990926.slip.lzh
```

The version of these modules released with MSHEAR 36/09-0531 were;

<code>/h0/isp98/cmds/ifslip</code>	version 11	crc \$2686D0	edition #21
<code>/h0/overlays/4120/5x8530</code>	version 23	crc \$A391B3	edition #22

The new versions are;

<code>/h0/isp98/cmds/ifslip</code>	version 12	crc \$1D0880	edition #21
<code>/h0/overlays/4120/5x8530</code>	version 26	crc \$DD5D03	edition #26

Use the crc to uniquely identify the module. The determine what version is loaded in memory, enter;

```
sysop: ident -m ifslip
Header for:  ifslip
Module size:  $26EC  #9964
Owner:        0.0
Module CRC:   $1D0880  Good CRC          <<==== look at this value
Header parity: $2564  Good parity
Edition:      $15     #21
Ty/La At/Rev  $E01    $A001
Permission:   $555    ----e-r-e-r-e-r
Dev Drv, 68000 obj, Sharable, System State Process
```

For more details of the versions and the filesystem organization see Version Details below.

## **Additional Details Section**

### **Diagnostic Details**

VSP) date  
August 19, 1999 Thursday 10:00:06 pm

VSP) slipstat /sl2

=====

#### IFSLIP Device Information Statistics:

-----  
Device = sl2            Driver = ifslip  
MTU    = 1006 bytes  
Flags = 0x0132 [ BROADCAST PT\_TO\_PT NO-TRAILERS NO-ARP ]

if\_this = 0x00e38190 if\_next = 0x00eb5290 if\_prev = 0x00e30010  
if\_static = 0x00e31990 if\_size = 0x000000d0

#### Socket Address (Internet Style):

-----  
Address Family = 2    IP Port = 0            IP Address = 131.215.58.9

#### IFSLIP Driver Static Storage:

-----

	Input	Output
	-----	-----
Serial Device:	/x2	/x2
Process ID's:	19	20
Compression:	OFF	OFF
Mbuf Queue Head:	0x00000000	0x00e0ca10
Bytes In/Out:	68908970	1438618817
IP Packets In/Out:	1823507	2844113
Compressed Packets:	187430	0
Uncompressed Packets:	23299	0
Biggest IP Packet:	414	552
Smallest IP Packet:	3	40
Errors:	409832	0

Reopens: 0 0  
System path: 20 21  
Death Flag: 0 0

Mbuf Size: 4096  
Failed InMbuf Alloc: 0  
Runts: 6896  
GS\_READY Polls: 9621394  
SS\_SIG Waits: 9621394

IFSLIP Device Descriptor Options:

-----  
Serial Device - Input: /x2  
Serial Device - Output: /x2  
Process Priority - Input: 128  
Process Priority - Output: 128  
Receive Buffer Size: 4096  
Compression: OFF  
Parity-Stop Bits-Bits/Char: 0x00  
Baud Rate Code: 0x0f

=====  
VSP) ifcontrol /sl2  
mbuf control module revision: 1  
total mbuf size: 393216  
total allocated: 15552  
minimum reserve: 49152  
failed attempts: 0  
allocation mode: NO WAIT  
looking for if control module ifi.83D73A09  
if control module revision: 1  
ip address: 83D73A09  
if device name: sl2  
total queued on xmit: 13700  
xmit queue limit: 15000  
discarded xmit bytes: 257912912  
discarded xmit packets: 470644  
total queued on rcv: 0  
discarded rcv packets: 0  
queued bytes in serial xmit buffer: 1024  
total input packets: 1406780  
total output packets: 2844169

A second report is obtained five minutes later.

VSP) date  
August 19, 1999 Thursday 10:06:12 pm

VSP) slipstat /sl2

=====  
IFSLIP Device Information Statistics:  
-----

Device = sl2 Driver = ifslip  
MTU = 1006 bytes  
Flags = 0x0132 [ BROADCAST PT\_TO\_PT NO-TRAILERS NO-ARP ]

if\_this = 0x00e38190 if\_next = 0x00eb5290 if\_prev = 0x00e30010  
if\_static = 0x00e31990 if\_size = 0x000000d0

Socket Address (Internet Style):

-----  
Address Family = 2 IP Port = 0 IP Address = 131.215.58.9

IFSLIP Driver Static Storage:

-----  
                  Input          Output  
                  -----          -----  
Serial Device:      /x2          /x2  
Process ID's:      19          20  
Compression:       OFF          OFF  
Mbuf Queue Head:   0x00000000    0x00e27350  
Bytes In/Out:      68908970    1439210109  
IP Packets In/Out:  1823507      2845192  
Compressed Packets:  187430          0  
Uncompressed Packets:  23299          0  
Biggest IP Packet:  414          552  
Smallest IP Packet:  3          40  
Errors:            409832          0  
Reopens:           0          0  
System path:       20          21  
Death Flag:        0          0  
  
Mbuf Size:          4096  
Failed InMbuf Alloc:  0  
Runts:              6896  
GS\_READY Polls:      9621394  
SS\_SIG Waits:       9621394

IFSLIP Device Descriptor Options:

-----  
Serial Device - Input:  /x2  
Serial Device - Output:  /x2  
Process Priority - Input:  128  
Process Priority - Output:  128  
Receive Buffer Size:      4096  
Compression:          OFF  
Parity-Stop Bits-Bits/Char:  0x00  
Baud Rate Code:          0x0f

-----  
VSP) infcontrol /sl2  
mbuf control module revision: 1  
total mbuf size: 393216  
total allocated: 13248  
minimum reserve: 49152

failed attempts: 0  
allocation mode: NO WAIT  
looking for if control module ifi.83D73A09  
if control module revision: 1  
ip address: 83D73A09  
if device name: sl2  
total queued on xmit: 12056  
xmit queue limit: 15000  
discarded xmit bytes: 258174308  
discarded xmit packets: 471121  
total queued on rcv: 0  
discarded rcv packets: 0  
queued bytes in serial xmit buffer: 604  
total input packets: 1406780  
total output packets: 2845252

## Module Version Details

The slip driver is located in /h0/isp98/cmds as ifslip.11 for the old version and ifslip.12 as the new version. The module used by the system is /h0/isp98/cmds/ifslip and is a copy of ifslip.12.

sysop: ident ifslip.11  
Header for: ifslip  
Module size: \$264A #9802  
Owner: 0.0  
Module CRC: \$2686D0 Good CRC  
Header parity: \$25C2 Good parity  
Edition: \$15 #21  
Ty/La At/Rev \$E01 \$A001  
Permission: \$555 ----e-r-e-r-e-r  
Dev Drv, 68000 obj, Sharable, System State Process

sysop: ident ifslip.12  
Header for: ifslip  
Module size: \$26EC #9964  
Owner: 0.0  
Module CRC: \$1D0880 Good CRC  
Header parity: \$2564 Good parity  
Edition: \$15 #21  
Ty/La At/Rev \$E01 \$A001  
Permission: \$555 ----e-r-e-r-e-r  
Dev Drv, 68000 obj, Sharable, System State Process

The serial port descriptor for Q4120 and Q730 systems is located in /h0/overlays/4120. The old version is located in a subdirectory 23/5x8530 while the new version is in another subdirectory 26/5x8530. The module used by the system is /h0/overlays/4120/5x8530 and is a copy of 26/5x8530. The module used by Q680 systems is /h0/overlays/147/5x8530 or /h0/overlays/00/5x8530 depending on the CPU type. Installing the lharc file will not update these Q680 serial port descriptors but the slip driver will avoid the error.

Module released with MSHEAR 36/09-0531

sysop: ident 23/5x8530  
Header for: 5x8530  
Module size: \$1120 #4384  
Owner: 0.0  
Module CRC: \$A391B3 Good CRC  
Header parity: \$1E75 Good parity  
Edition: \$16 #22  
Ty/La At/Rev \$E01 \$A001  
Permission: \$555 ----e-r-e-r-e-r  
Dev Drv, 68000 obj, Sharable, System State Process

Revised Module:  
sysop: ident 26/5x8530  
Header for: 5x8530  
Module size: \$1160 #4448  
Owner: 0.0  
Module CRC: \$DD5D03 Good CRC  
Header parity: \$1E79 Good parity  
Edition: \$1A #26  
Ty/La At/Rev \$E01 \$A001  
Permission: \$555 ----e-r-e-r-e-r  
Dev Drv, 68000 obj, Sharable, System State Process

## Configuration Details

Portion of desired Key file for a SLIP link:

ws1 6  
ws2 6  
resend1 2  
resend2 2  
rspkt1 3  
rspkt2 3

This produces the desired comlink configuration section of aqcfg:

```
* comlink section for IP mode on pri
*
[pri]
levels=32 mprio=20 port=35145 ipaddr=131.215.63.5 pkts=2500
fmt=QSL rce=y
resend=2 maxresends=15 synctime=20 ws=6
resendpkts=3 netdly=120 netto=60 delay=5
grpsize=1 grpto=0 detprio=14 timeprio=24
notify=y station=GOR udp=y keepnew=y
*
* comlink section for IP mode on sec
*
[sec]
levels=32 mprio=20 port=37145 ipaddr=131.215.63.6 pkts=2500
fmt=QSL rce=y
resend=2 maxresends=15 synctime=20 ws=6
resendpkts=3 netdly=120 netto=60 delay=5
grpsize=1 grpto=0 detprio=14 timeprio=24
notify=y station=GOR udp=y keepnew=y
```

\*

Portion of the key file which caused the error when both comlinks became active. Note that the correct key is resendpkts=%rspkt1%.

```
ws1 6
ws2 6
resend1 2
resend2 2
rspkts1 3
rspkts2 3
```

That produces the desired comlink configuration section of aqcfg, the default keyvalue of 6 is used for resendpkt, rather than 2:

\* comlink section for IP mode on pri

\*

```
[pri]
levels=32 mprio=20 port=35145 ipaddr=131.215.63.5 pkts=2500
fmt=QSL rce=y
resend=2 maxresends=15 synctime=20 ws=6
resendpkts=6 netdly=120 netto=60 delay=5
grpsize=1 grpto=0 detprio=14 timeprio=24
notify=y station=GOR udp=y keepnew=y
```

\*

\*

\* comlink section for IP mode on sec

\*

```
[sec]
levels=32 mprio=20 port=37145 ipaddr=131.215.63.6 pkts=2500
fmt=QSL rce=y
resend=2 maxresends=15 synctime=20 ws=6
resendpkts=6 netdly=120 netto=60 delay=5
grpsize=1 grpto=0 detprio=14 timeprio=24
notify=y station=GOR udp=y keepnew=y
```

\*