






b_1	$w_{1,2}$	0	0	$w_{1,5}$	0	0	0	0	0	0	0	0	0	0	0
$w_{1,2}$	b_2	$w_{2,3}$	0	0	$w_{2,6}$	0	0	0	0	0	0	0	0	0	0
0	$w_{2,3}$	b_3	$w_{3,4}$	0	0	$w_{3,7}$	0	0	0	0	0	0	0	0	0
0	0	$w_{3,4}$	b_4	0	0	0	$w_{4,8}$	0	0	0	0	0	0	0	0
$w_{1,5}$	0	0	0	b_5	$w_{5,6}$	0	0	$w_{5,9}$	0	0	0	0	0	0	0
0	$w_{2,6}$	0	0	$w_{5,6}$	b_6	$w_{6,7}$	0	0	$w_{6,10}$	0	0	0	0	0	0
0	0	$w_{3,7}$	0	0	$w_{6,7}$	b_7	$w_{7,8}$	0	0	$w_{7,11}$	0	0	0	0	0
0	0	0	$w_{4,8}$	0	0	$w_{7,8}$	b_8	0	0	$w_{8,12}$	0	0	0	0	0
0	0	0	0	$w_{5,9}$	0	0	0	b_9	$w_{9,10}$	0	0	$w_{9,13}$	0	0	0
0	0	0	0	0	$w_{6,10}$	0	0	$w_{9,10}$	b_{10}	$w_{10,11}$	0	0	$w_{10,14}$	0	0
0	0	0	0	0	0	$w_{7,11}$	0	0	$w_{10,11}$	b_{11}	$w_{11,12}$	0	0	$w_{11,15}$	0
0	0	0	0	0	0	0	$w_{8,12}$	0	0	$w_{11,12}$	b_{12}	0	0	0	$w_{12,16}$
0	0	0	0	0	0	0	$w_{9,13}$	0	0	$w_{13,14}$	b_{13}	0	0	$w_{13,14}$	0
0	0	0	0	0	0	0	0	$w_{10,14}$	0	0	$w_{13,14}$	b_{14}	$w_{14,15}$	0	0
0	0	0	0	0	0	0	0	0	$w_{11,15}$	0	0	$w_{14,15}$	b_{15}	$w_{15,16}$	0
0	0	0	0	0	0	0	0	0	0	$w_{12,16}$	0	0	$w_{15,16}$	b_{16}	0

b)	f_1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	0	f_2	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	0	0	f_3	0	0	0	0	0	0	0	0	0	0	0	0	0
	0	0	0	f_4	0	0	0	0	0	0	0	0	0	0	0	0
	0	0	0	0	f_5	0	0	0	0	0	0	0	0	0	0	0
	0	0	0	0	0	f_6	0	0	0	0	0	0	0	0	0	0
	0	0	0	0	0	0	f_7	0	0	0	0	0	0	0	0	0
	0	0	0	0	0	0	0	f_8	0	0	0	0	0	0	0	0
	0	0	0	0	0	0	0	0	f_9	0	0	0	0	0	0	0
	0	0	0	0	0	0	0	0	0	f_{10}	0	0	0	0	0	0
	0	0	0	0	0	0	0	0	0	0	f_{11}	0	0	0	0	0
	0	0	0	0	0	0	0	0	0	0	0	f_{12}	0	0	0	0
	0	0	0	0	0	0	0	0	0	0	0	0	f_{13}	0	0	0
	0	0	0	0	0	0	0	0	0	0	0	0	0	f_{14}	0	0
	0	0	0	0	0	0	0	0	0	0	0	0	0	f_{15}	0	0
	0	0	0	0	0	0	0	0	0	0	0	0	0	0	f_{16}	0




$$FS = \frac{\mathbf{x}^T \mathbf{R} \mathbf{x}}{\mathbf{x}^T \mathbf{F} \mathbf{x}} = \frac{x}{x^T x}$$







a.



b.




c.




d.


X

e.







a.




b.



C.



d.



e.

